

PRELIMINARY SUMMARY OF MAP ACTIONS

MARCH 12, 2015

Community: OAK HARBOR, CITY OF

Community No: 530068

To assist your community in maintaining the Flood Insurance Rate Map (FIRM), we have summarized below the previously issued Letter of Map Change (LOMC) actions (i.e., Letters of Map Revision (LOMRs) and Letters of Map Amendment (LOMAs)) that will be affected by the preparation of the enclosed revised FIRM panel(s).

1. LOMCs Incorporated

The modifications effected by the LOMCs listed below have been reflected on the Preliminary copies of the revised FIRM panels. In addition, these LOMCs will remain in effect until the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMR	05-10-0704P	12/06/2005	Oak Harbor Home Depot	53029C0120E	53029C0120F

2. LOMCs Not Incorporated

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because of scale limitations or because the LOMC issued had determined that the lot(s) or structure(s) involved were outside the Special Flood Hazard Area, as shown on the FIRM. These LOMCs will be revalidated free of charge 1 day after the revised FIRM becomes effective through a single revalidation letter that reaffirms the validity of the previous LOMCs.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	199532493MBJ	04/06/1978	ELY'S ADDITION, LOTS 46-48	530068_03A	53029C0120F
LOMA	95-R10-061	02/23/1995	PATTON'S WOODLAWN ESTATES, DIV 1, LOT 5 -- 7149 70TH NW	5300680005C	53029C0120F
LOMA	04-10-0085A	11/12/2003	PATTON'S WOODLAWN ESTATES, DIV NO. 1, LOT 5 -- 721 SE CASTLE PARK COURT	53029C0120E	53029C0120F
LOMA	08-10-0164A	03/28/2008	PATTONS WOODLAWN ESTATES, LOT 6 -- 781 SE CASTLE PARK COURT	53029C0120E	53029C0120F
LOMA	10-10-0568A	04/15/2010	LOT 3, DRIFTWOOD BEACH -- 2164 DILLARD LANE	53029C0120E	53029C0120F

3. LOMCs Superseded

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because they are being superseded by new detailed flood hazard information or the information available was not sufficient to make a determination. The reason each is being superseded is noted below. These LOMCs will no longer be in effect when the revised FIRM becomes effective.

PRELIMINARY SUMMARY OF MAP ACTIONS

Community: OAK HARBOR, CITY OF

Community No: 530068

LOMC	Case No.	Date Issued	Project Identifier	Reason Determination Will be Superseded
102	89-10-09P	03/27/1989		1
LOMA	00-R10-001	02/09/2000	PATTON'S WOODLAND ESTATES, DIV 1, LOT 4 -- 700 SE CASTLE PARK COURT	1
LOMA	12-10-0050A	10/25/2011	LOT 1 AND TRACT B -- 1551 SOUTH BEEKSMA DRIVE	4

1. Insufficient information available to make a determination.
2. Lowest Adjacent Grade and Lowest Finished Floor are below the proposed Base Flood Elevation.
3. Lowest Ground Elevation is below the proposed Base Flood Elevation.
4. Revised hydrologic and hydraulic analyses.
5. Revised topographic information.

4. LOMCs To Be Redetermined

The LOMCs in Category 2 above will be revalidated through a single revalidation letter that reaffirms the validity of the determination in the previously issued LOMC. For LOMCs issued for multiple lots or structures where the determination for one or more of the lots or structures has changed, the LOMC cannot be revalidated through this administrative process. Therefore, we will review the data previously submitted for the LOMC requests listed below and issue a new determination for the affected properties after the effective date of the revised FIRM.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		