File Original and First Copy with Department of Ecology
Second Copy — Owner's Copy
Third Copy — Driller's Copy

WATER WELL REPORT

STATE OF WASHINGTON

Start Card No. W074169
UNIQUE WELL I.D. #
Water Right Permit No.

OWNER: Name R.H. Loutzenhiser Address 228 N. Goodrich Rd. Camano Isl 98292

(2) LOCATION OF WELL: County Island SE 1/4 NW 1/4 Sec 32 T. 32 N. R. 3 E W.M.

(2a) STREET ADDRESS OF WELL (or nearest address) SAME

(3) PROPOSED USE: [X] Domestic [ ] Irrigation [ ] DeWater Industrial [ ] Test Well [ ] Municipal [ ] Other [ ]

(4) TYPE OF WORK: Owner's number of well (If more than one)
Abandoned [ ] New well [X] Deepened [ ] Reconditioned [ ] Method: Dug [ ] Cable [X] Rotary [ ] Bored [ ] Driven [ ] Jetted [ ]

(5) DIMENSIONS: Diameter of well 6 inches.
Drilled 185-10½" feet. Depth of completed well 185-10½ ft.

(6) CONSTRUCTION DETAILS:
Casing installed: 6 " Diam. from +2-11" ft. to 174-10½
Welded [X] " Diam. from ft. to ft.
Liner installed [ ] " Diam. from ft. to ft.
Threaded [ ]

Perforations: Yes [ ] No [X]
Type of perforator used
SIZE of perforations in. by in.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.

Screens: Yes [X] No [ ]
Manufacturer's Name HOUSTON
Type SS Model No.
Diam. 5 Slot size 10 from 185-10½ ft. to 174-8 ft.
Diam. Slot size from ft. to ft.

Gravel packed: Yes [ ] No [X] Size of gravel
Gravel placed from ft. to ft.

Surface seal: Yes [X] No [ ] To what depth? 18 ft.
Material used in seal BENTONITE
Did any strata contain unusable water? Yes [ ] No [X]
Type of water? Depth of strata
Method of sealing strata off

(7) PUMP: Manufacturer's Name GRUNDFOSS
Type: SUBMERSABLE H.P. 3

(8) WATER LEVELS: Land-surface elevation above mean sea level ft.
Static level 143-7 ft. below top of well Date 2-9-98
Artesian pressure lbs. per square inch Date
Artesian water is controlled by (Cap, valve, etc.)

(9) WELL TESTS: Drawdown is amount water level is lowered below static level SERVICE
Was a pump test made? Yes [X] No [ ] If yes, by whom? ISLAND PUMP
Yield: 30+ gal./min. with 4-2" ft. drawdown after 4 hrs.
" " " "
" " " "

Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)

Time	Water Level	Time	Water Level	Time	Water Level

Date of test
Bailer test gal./min. with ft. drawdown after hrs.
Airtest gal./min. with stem set at ft. for hrs.
Artesian flow g.p.m. Date
Temperature of water Was a chemical analysis made? Yes [X] No [ ]

(10) WELL LOG or ABANDONMENT PROCEDURE DESCRIPTION

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of information.

MATERIAL	FROM	TO
TOP SOIL	0	2
GRAY HARD PAN	2	85
BROWN CLAY	85	96
GRAY HARD PAN	96	103
GRAY SAND ROCKS	103	124
GRAY HARD PAN	124	135
BROWN HARD PAN	135	156
SAND GRAVEL WATER	156	186

This well meets all Co. & State Regulations at time it was drilled
Gene Hitt
2-19-98

Work Started 12-11-97 19. Completed 2-15 19 98

WELL CONSTRUCTOR CERTIFICATION:

I constructed and/or accept responsibility for construction of this well, and its compliance with all Washington well construction standards. Materials used and the information reported above are true to my best knowledge and belief.

NAME Gene's Well Drilling (PERSON, FIRM, OR CORPORATION) (TYPE OR PRINT)

Address 5115 268th St. N.W. Stanwood, Wa. 98292

(Signed) Lawrence Otto Kuper (WELL DRILLER) License No. 2349

Contractor's Registration No. GENESWOOTICC Date 2-19 19 98

(USE ADDITIONAL SHEETS IF NECESSARY)

Ecology is an Equal Opportunity and Affirmative Action employer. For special accommodation needs, contact the Water Resources Program at (206) 407-6600. The TDD number is (206) 407-6006.

C