File Original and First Copy with Department of Ecology
Second Copy — Owner's Copy
Third Copy — Driller's Copy 29/3E/17/M

WATER WELL REPORT

STATE OF WASHINGTON

Application No. 29/03-17M
Permit No.

(1) OWNER: Name VERLANE GABELEIN Address BOX 950 CLINTON, WASH. 98236

(2) LOCATION OF WELL: County ISLAND - THE S½ OF THE NE¼ NW¼ SW¼ Sec. 17 T. 29 N., R. 3E W.M.

Bearing and distance from section or subdivision corner 1320 No. & 1320 EAST OF THE S.W. CORNER OF SECT. 17

(3) PROPOSED USE: Domestic ☒ Industrial ☐ Municipal ☐ Irrigation ☐ Test Well ☐ Other ☐

(4) TYPE OF WORK: Owner's number of well (if more than one)

New well ☒ Deepened ☐ Reconditioned ☐

Method: Dug ☐ Bored ☐ Cable ☒ Driven ☐ Rotary ☐ Jetted ☐

(5) DIMENSIONS: Diameter of well 6 inches.

Drilled 150 ft. Depth of completed well 149 ft.

(6) CONSTRUCTION DETAILS:

Casing installed: ..." Diam. from ... ft. to ... ft.

Threaded ☐ ..." Diam. from ... ft. to ... ft.

Welded ☒ 6" Diam. from +1 ft. to 143 ft.

Perforations: Yes ☐ No ☒

Type of perforator used

SIZE of perforations in. by in.

perforations from ft. to ft.

perforations from ft. to ft.

perforations from ft. to ft.

Screens: Yes ☒ No ☐

Manufacturer's Name JOHNSON

Type SS-WRBE Model No 6x5x25

Diam. 6 Slot size 25 from 143 ft. to 149 ft.

Diam. Slot size from ft. to ft.

Gravel packed: Yes ☐ No ☒ Size of gravel:

Gravel placed from ft. to ft.

Surface seal: Yes ☒ No ☐ To what depth? 18 ft.

Material used in seal BENTONITE

Did any strata contain unusable water? Yes ☐ No ☒

Type of water? Depth of strata

Method of sealing strata off

(7) PUMP: Manufacturer's Name Goulds

Type: 13 EM 10412 H.P. 1

(8) WATER LEVELS: Land-surface elevation above mean sea level 105 ft.

Static level 113 ft. below top of well Date 6-15-74

Artesian pressure — lbs. per square inch Date —

Artesian water is controlled by — (Cap, valve, etc.)

(9) WELL TESTS: Drawdown is amount water level is lowered below static level

Was a pump test made? Yes ☒ No ☐ If yes, by whom? 0058

Yield: 22 gal./min. with 3 ft. drawdown after 4 hrs.

" " " "

" " " "

Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)

Time	Water Level	Time	Water Level	Time	Water Level
1430	113'				
1830	116'				
1831	113'				

Date of test 6-15-74

Bailer test 45 gal./min. with 2 ft. drawdown after 1/4 hrs.

Artesian flow — g.p.m. Date —

Temperature of water 47 Was a chemical analysis made? Yes ☒ No ☐

(10) WELL LOG:

Formation: *Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.*

MATERIAL	FROM	TO
HARD PAN - ROCKS TO 4" DIA	0'	5'
PIT RUN GRAVEL & SAND	5'	39'
MED. SAND - BROWN - NON	39'	49'
PEA GRAVEL - ROCKS TO 2"	49'	68'
COARSE SAND - BROWN - NON	68'	89'
BLUE CLAY	89'	90'
FINE SAND - GRAY - NON	90'	112'
MED. SAND - BLUE - BEAR	112'	113'
COARSE SAND - BLUE - BEARING	113'	149'
BLUE CLAY - PULL BACK	149'	150'

Work started MAY 25, 19 74 Completed JUNE 14, 19 74

WELL DRILLER'S STATEMENT:

This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME SOUTH ISLAND WELL CONSTRUCTORS (Person, firm, or corporation) (Type or print)

Address 2918 E. BECKER Rd. CLINTON WASH. 98236

[Signed] William L. Benton (Well Driller)

License No. 0058 Date JUNE 21, 19 74

(USE ADDITIONAL SHEETS IF NECESSARY)

S. F. No. 7356—OS—(Rev. 4-71).