The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.

File Original with
Department of Ecology
Second Copy - Owner's Copy
Third Copy - Driller's Copy

WATER WELL REPORT

STATE OF WASHINGTON

ENTERED

Notice of Intent W 09943
UNIQUE WELL I.D # ABD 986
Water Right Permit No.

(1) OWNER: Name PETE MORGAN Address 1384 S.W. KALAMA Loop, OAKHARBOR 98

(2) LOCATION OF WELL: County ISLAND NE 1/4 NE 1/4 Sec 29 T 33 N R 2E WM

(2a) STREET ADDRESS OF WELL: (or nearest address) 5 A DEVRIES Rd, OAK HARBOR 98277

TAX PARCEL NO.: R 233 29 417 4310

33-2E-29A

(3) PROPOSED USE: [X] Domestic [ ] Industrial [ ] Municipal [ ] Irrigation [ ] Test Well [ ] Other [ ] DeWater

(4) TYPE OF WORK: Owner's number of well (if more than one) 1
[X] New Well [ ] Deepened [ ] Reconditioned [ ] Decommission
Method: [ ] Dug [X] Cable [ ] Rotary [ ] Bored [ ] Driven [ ] Jetted

(5) DIMENSIONS: Diameter of well 6 inches
Drilled 206 feet. Depth of completed well 206 ft.

(6) CONSTRUCTION DETAILS
Casing Installed:
[X] Welded 6" Diam. from 0 ft. to 201 ft.
[ ] Liner installed " Diam. from ft. to ft.
[ ] Threaded " Diam from ft. to ft.

Perforations: [ ] Yes [X] No
Type of perforator used
SIZE of perforations in. by in.
perforations from ft. to ft.

Screens: [X] Yes [ ] No [ ] K-Pac Location 200
Manufacturer's Name COOK
Type STAINLESS Model No. 304
Diam. 6 Slot Size 10 from 201 ft. to 206 ft.
Diam. Slot Size from ft. to ft.

Gravel/Filter packed: [ ] Yes [X] No [ ] Size of gravel/sand
Material placed from ft. to ft.

Surface seal: [X] Yes [ ] No To what depth? 20 ft.
Material used in seal BENTONITE
Did any strata contain unusable water? [ ] Yes [X] No
Type of water? Depth of strata
Method of sealing strata off

(7) PUMP: Manufacturer's Name
Type: H.P.

(8) WATER LEVELS: Land-surface elevation above mean sea level 270 ft.
Static level 184 ft. below top of well Date 8-99
Artesian pressure lbs. per square inch Date
Artesian water is controlled by (Cap, valve, etc.)

(9) WELL TESTS: Drawdown is amount water level is lowered below static level
Was a pump test made? [ ] Yes [X] No If yes, by whom?
Yield: gal./min. with ft. drawdown after hrs.
Yield: gal./min. with ft. drawdown after hrs.
Yield: gal./min. with ft. drawdown after hrs.
Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)

Time	Water Level	Time	Water Level	Time	Water Level

Date of test
Bailer test 10 gal./min. with 10 ft. drawdown after 3 hrs.
Airtest gal./min. with ft. drawdown after hrs.
Artesian flow g.p.m. Date
Temperature of water Was a chemical analysis made? [ ] Yes [X] No

(10) WELL LOG or DECOMMISSIONING PROCEDURE DESCRIPTION
Formation: Describe by color, character, size of material and structure, and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of information. Indicate all water encountered.

MATERIAL	FROM	TO
HARD PAN	0	112
GRAVEL	112	150
SAND	150	185
CLAY	185	192
WATER IN SAND	192	206

RECEIVED
SEP 02 1999
DEPT OF ECOLOGY

Work Started Aug. 99 Completed Aug 27 99

WELL CONSTRUCTION CERTIFICATION:

I constructed and/or accept responsibility for construction of this well, and its compliance with all Washington well construction standards. Materials used and the information reported above are true to my best knowledge and belief.

Type or Print Name DENNIS FABER License No 129
(Licensed Driller/Engineer)

Trainee Name — License No. —

Drilling Company WHIDBEY DRILLERS

(Signed) Dennis Faber License No 129
(Licensed Driller/Engineer)

Address OAK HARBOR WA 98277

Contractor's Registration WHIDBWD289 MM Date Aug 99

(USE ADDITIONAL SHEETS IF NECESSARY)

Ecology is an Equal Opportunity and Affirmative Action employer. For accommodation needs, contact the Water Resources Program at (360) 407-6600. The TDD number is (360) 407-6006.

ECY 050-1-20 (11/98)