BK4

Start Card No. _____

UNIQUE WELL I.D. # _____

Water Right Permit No. _____

WATER WELL REPORT

STATE OF WASHINGTON

...Copy with ...gy
Owner's Copy
Driller's Copy

...ER: Name Odd Fellow Park Address 96 South Camano Ridge Road-Camano Isla

...OCATION OF WELL: County Island n.E. 1/4 1/4 Sec 2 T. 31 N. R. 2 E W.M.

STREET ADDRESS OF WELL (or nearest address) 96 South Camano Ridge Road

(3) PROPOSED USE: [X] Domestic [ ] Irrigation [ ] DeWater Industrial [ ] Test Well [ ] Municipal [ ] Other [ ]

(4) TYPE OF WORK: Owner's number of well (if more than one) _____
Abandoned [ ] New well [X] Deepened [ ] Reconditioned [ ] Method: Dug [ ] Cable [X] Rotary [ ] Bored [ ] Driven [ ] Jetted [ ]

(5) DIMENSIONS: Diameter of well 6 inches.
Drilled 46 feet. Depth of completed well 46 ft.

(6) CONSTRUCTION DETAILS:
Casing installed: 6 " Diam. from +2 ft. to 42 ft.
Welded [X] " Diam. from _____ ft. to _____ ft.
Liner installed [ ] " Diam. from _____ ft. to _____ ft.
Threaded [ ]

Perforations: Yes [ ] No [X]
Type of perforator used _____
SIZE of perforations _____ in. by _____ in.
_____ perforations from _____ ft. to _____ ft.
_____ perforations from _____ ft. to _____ ft.
_____ perforations from _____ ft. to _____ ft.

Screens: Yes [X] No [ ]
Manufacturer's Name Cook
Type S. Steel Model No. _____
Diam. 5 Slot size 14 from 42 ft. to 46 ft.
Diam. _____ Slot size _____ from _____ ft. to _____ ft.

Gravel packed: Yes [ ] No [X] Size of gravel _____
Gravel placed from _____ ft. to _____ ft.

Surface seal: Yes [X] No [ ] To what depth? 18 ft.
Material used in seal Benonite
Did any strata contain unusable water? Yes [ ] No [X]
Type of water? _____ Depth of strata _____
Method of sealing strata off _____

(7) PUMP: Manufacturer's Name _____
Type: _____ H.P. _____

(8) WATER LEVELS: Land-surface elevation above mean sea level _____ ft.
Static level _____ ft. below top of well Date _____
Artesian pressure _____ lbs. per square inch Date _____
Artesian water is controlled by _____ (Cap, valve, etc.)

(9) WELL TESTS: Drawdown is amount water level is lowered below static level
Was a pump test made? Yes [ ] No [ ] If yes, by whom? _____
Yield: _____ gal./min. with _____ ft. drawdown after _____ hrs.
" " " "
" " " "

Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)

Time	Water Level	Time	Water Level	Time	Water Level

Date of test _____
Bailer test _____ gal./min. with _____ ft. drawdown after _____ hrs.
Airtest _____ gal./min. with stem set at _____ ft. for _____ hrs.
Artesian flow _____ g.p.m. Date _____
Temperature of water _____ Was a chemical analysis made? Yes [ ] No [X]

(10) WELL LOG or ABANDONMENT PROCEDURE DESCRIPTION

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of information.

MATERIAL	FROM	TO
Top-soil	0	2
Hard-pan	2	23
Hard-pan - cemented gravel	23	39
water - sand - gravel	39	46

#2 well
42' open interval

Work Started 4-15-76 18. Completed 4-20 1976

WELL CONSTRUCTOR CERTIFICATION:

I constructed and/or accept responsibility for construction of this well, and its compliance with all Washington well construction standards. Materials used and the information reported above are true to my best knowledge and belief.

NAME Hitt Well Drilling (PERSON, FIRM, OR CORPORATION) (TYPE OR PRINT)

Address 28926 54th Ave NW. Stanwood, WA.

(Signed) Everett Hitt (WELL DRILLER) License No. 0187

Contractor's Registration No. _____ Date 4-24 1976

(USE ADDITIONAL SHEETS IF NECESSARY)

Ecology is an Equal Opportunity and Affirmative Action employer. For special accommodation needs, contact the Water Resources Program at (206) 407-6600. The TDD number is (206) 407-6006.

ECY 050-1-20 (9/93)