File Original and First Copy with Department of Ecology
Second Copy — Owner's Copy
Third Copy — Driller's Copy

ENTERED

WATER WELL REPORT

STATE OF WASHINGTON

Start Card No. W054340
UNIQUE WELL I.D. #
Water Right Permit No. 32-2E-23F

(1) OWNER: Name Maple Grove Water Ass'N. Address 654 W Maple Grove Rd Camano Is.

(2) LOCATION OF WELL: County Island SE 1/4 NW 1/4 Sec 23 T 32 N., R 2 E W.M.

(2a) STREET ADDRESS OF WELL (or nearest address) 628 W North Camano Dr. Camano Is. Wa. 98292

(3) PROPOSED USE: ☑ Domestic ☐ Irrigation ☐ DeWater Industrial ☐ Test Well ☐ Municipal ☐ Other ☐

(4) TYPE OF WORK: Owner's number of well (If more than one)
Abandoned ☐ New well ☑ Deepened ☐ Reconditioned ☐
Method: Dug ☐ Cable ☐ Rotary ☑ Bored ☐ Driven ☐ Jetted ☐

(5) DIMENSIONS: Diameter of well 6 inches.
Drilled 68 feet. Depth of completed well 68 ft.

(6) CONSTRUCTION DETAILS:
Casing Installed: 6" Diam. from 0 ft. to 58 ft.
Welded ☑ Liner installed ☐ Threaded ☐
" Diam. from ft. to ft.
" Diam. from ft. to ft.

Perforations: Yes ☐ No ☑
Type of perforator used
SIZE of perforations in. by in.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.

Screens: Yes ☑ No ☐
Manufacturer's Name Houston
Type Stainless Steel Model No.
Diam. 5" Slot size 12 from 58 ft. to 63 ft.
Diam. 5" Slot size 8 from 63 ft. to 68 ft.

Gravel packed: Yes ☐ No ☑ Size of gravel
Gravel placed from ft. to ft.

Surface seal: Yes ☑ No ☐ To what depth? 20' ft.
Material used in seal Bentonite
Did any strata contain unusable water? Yes ☐ No ☑
Type of water? Depth of strata
Method of sealing strata off

(7) PUMP: Manufacturer's Name unknown
Type: H.P.

(8) WATER LEVELS: Land-surface elevation above mean sea level ft.
Static level 48' ft. below top of well Date 2-15-96
Artesian pressure lbs. per square inch Date
Artesian water is controlled by (Cap, valve, etc.)

(9) WELL TESTS: Drawdown is amount water level is lowered below static level
Was a pump test made? Yes ☐ No ☑ If yes, by whom?
Yield: gal./min. with ft. drawdown after hrs.
" " " "
" " " "

Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)

Time	Water Level	Time	Water Level	Time	Water Level

Date of test
Bailer test gal./min. with ft. drawdown after hrs.
Airtest 30 gal./min. with stem set at 68 ft. for 1 1/2 hrs.
Artesian flow g.p.m. Date
Temperature of water Was a chemical analysis made? Yes ☐ No ☑

(10) WELL LOG or ABANDONMENT PROCEDURE DESCRIPTION

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of information.

MATERIAL	FROM	TO
Top Soil	0	2
Sand & Gravel	2	18
Gravel ~~muddy~~ (Dirty)	18	38
Grey Clay	38	50
gravel & clay	50	58
gravel with water	58	63
Sand (Grey) (Fine)	63	68

RECEIVED
MAR 04 1996
DEPT. OF ECOLOGY

Work Started 2-15-96, 19. Completed 2-15, 1996

WELL CONSTRUCTOR CERTIFICATION:

I constructed and/or accept responsibility for construction of this well, and its compliance with all Washington well construction standards. Materials used and the information reported above are true to my best knowledge and belief.

NAME Stein Well Drilling (PERSON, FIRM, OR CORPORATION) (TYPE OR PRINT)
Address 620 N. Wiberg ct. Camano Is.
(Signed) Don Stein (WELL DRILLER) License No. 1692
Contractor's Registration No. STEINWD055L9 Date 2-15, 1996

(USE ADDITIONAL SHEETS IF NECESSARY)

Ecology is an Equal Opportunity and Affirmative Action employer. For special accommodation needs, contact the Water Resources Program at (206) 407-6600. The TDD number is (206) 407-6006.

ECY 050-1-20 (9/93)