File Original with Department of Ecology 116583
Second Copy Owner's Copy
Third Copy Driller's Copy

WATER WELL REPORT

STATE OF WASHINGTON

Notice of Intent W 118541
UNIQUE WELL I D # ABO 904
Water Right Permit No

(1) OWNER Name Jeff Lecvick Address 28921 64th Ave NW Stanwood, WA

(2) LOCATION OF WELL County Island SW 1/4 SW 1/4 Sec 19 T 31 N R 03E WM

(2a) STREET ADDRESS OF WELL (or nearest address) xxx Sunrise Blvd Camano Isl WA 98282

TAX PARCEL NO R33220-009-0440

(3) PROPOSED USE ☒ Domestic ☐ Irrigation ☐ DeWater ☐ Industrial ☐ Test Well ☐ Municipal ☐ Other

(4) TYPE OF WORK Owner's number of well (if more than one)
☒ New Well ☐ Deepened ☐ Reconditioned ☐ Decommission
Method ☐ Dug ☒ Cable ☐ Rotary ☐ Bored ☐ Driven ☐ Jetted

(5) DIMENSIONS Diameter of well 6 inches
Drilled 137 feet Depth of completed well 137 ft

(6) CONSTRUCTION DETAILS
Casing Installed
☒ Welded 6 Diam from +2 ft to 128 ft
☐ Liner installed Diam from ft to ft
☐ Threaded Diam from ft to ft

Perforations ☐ Yes ☒ No
Type of perforator used
SIZE of perforations in by in
perforations from ft to ft

Screens ☒ Yes ☐ No ☐ K Pac Location 127
Manufacturer's Name Alloy
Type Model No
Diam 5 Slot Size 12 from 127 ft to 137 ft
Diam Slot Size from ft to ft

Gravel/Filter packed ☐ Yes ☒ No ☐ Size of gravel/sand
Material placed from ft to ft

Surface seal ☒ Yes ☐ No To what depth? 18 ft
Material used in seal Bentonite
Did any strata contain unusable water? ☐ Yes ☒ No
Type of water? Depth of strata
Method of sealing strata off

(7) PUMP Manufacturer's Name Goulds
Type SUB H P 3/4

(8) WATER LEVELS Land surface elevation above mean sea level ft
Static level 110 ft below top of well Date
Artesian pressure lbs per square inch Date
Artesian water is controlled by
(Cap valve etc)

(9) WELL TESTS Drawdown is amount water level is lowered below static level
Was a pump test made? ☒ Yes ☐ No If yes by whom? Gene's
Yield 15 gal/min with 3 ft drawdown after 2 hrs
Yield gal/min with ft drawdown after hrs
Yield gal/min with ft drawdown after hrs
Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)

Time	Water Level	Time	Water Level	Time	Water Level

Date of test 6-23-02
Bailer test gal/min with ft drawdown after hrs
Airtest gal/min with ft drawdown after hrs
Artesian flow g p m Date
Temperature of water Was a chemical analysis made? ☒ Yes ☐ No

(10) WELL LOG or DECOMMISSIONING PROCEDURE DESCRIPTION
Formation Describe by color character size of material and structure and the kind and nature of the material in each stratum penetrated with at least one entry for each change of information Indicate all water encountered

MATERIAL	FROM	TO
Top-soil	0	2
Br hard-pan	2	13
Gray Hard-pan	13	26
Br hard-pan	26	64
Br sandy-clay	64	72
Dry sand-gravel	72	119
Water sand-gravel	119	137

I certify this well meets all County-State rules and reg. at time it was drilled
Gene Hutt 6-25-02

RECEIVED
JUL 30 2002
DEPT OF ECOLOGY

Work Started 6-7 02 Completed 6-13-02

WELL CONSTRUCTION CERTIFICATION

I constructed and/or accept responsibility for construction of this well and its compliance with all Washington well construction standards Materials used and the information reported above are true to my best knowledge and belief

Type or Print Name License No
(Licensed Driller/Engineer)

Trainee Name License No
Drilling Company Gene's Well Drilling
(Signed) Gene Hutt License No 0186
(Licensed Driller/Engineer)
Address 5115 268th NW Stanwood, WA
Contractor's Registration No GENLSW007CC Date 6-25-02

(USE ADDITIONAL SHEETS IF NECESSARY)

Ecology is an Equal Opportunity and Affirmative Action employer For special accommodation needs contact the Water Resources Program at (360) 407 6600 The TDD number is (360) 407 6006

ECY 050 1 20 (11/98)